

1/54





FIG. 1

2/54



3/54




FIG. 3




FIG. 4B




FIG. 4A

5/54




FIG. 5




FIG. 6A




FIG. 6B




FIG. 6B1




FIG. 6C

7/54




FIG. 6D




FIG. 6E

8/54

FIG. 7A





FIG. 7B



9/54




FIG. 8A




FIG. 8B




FIG. 9A

12/54




FIG. 9B




FIG. 9C







FIG. 9D

13/54






FIG. 10A






FIG. 10B

16/54



17/54




FIG. 12A





FIG. 12B

18/54



19/54




FIG. 13B




FIG. 13D

20/54




FIG. 13C

21/54




FIG. 13E

22/54




FIG. 14A




FIG. 14B

23/54




FIG. 14C





FIG. 14D



25/54




FIG. 14F




FIG. 15A

TOE

HEEL

ZONE 1

ZONE 2

ZONE 3

ZONE 4

FIRM 60-65	FIRM 60-65	SOFT 30-35	FIRM 60-65
INSERT: PORON 4000-40-20125 OR BONTX LS1712 MED. 45-50			SOFT 30-35

FIG. 15B

27/54

FIRM 60-65	FIRM 60-65	MED. 45-50	MED. 45-50
MED. 45-50			

FIG. 15C

SLOW RECOVERY DIE-CUT INSERT (PORON 4800-92-12125)			
FIRM 60-65	FIRM 60-65	SOFT 30-35	FIRM 60-65
FIRM 60-65	SOFT 30-35		SOFT 30-35
MED. 45-50 AND OPTIONAL PLACEMENT OF MOLDED-IN SUPPORT INSERTS			

FIG. 15D




FIG. 15F

29/54





FIG. 16A



31/54




FIG. 17A

32/54




FIG. 17B




FIG. 18A

34/54




FIG. 18B




FIG. 18C




FIG. 18D

35/54




FIG. 18E




FIG. 18F




FIG. 18G

36/54




FIG. 19A

37/54




FIG. 19B

38/54




FIG. 19C

39/54




FIG. 19D

40/54




FIG. 19E




FIG. 19F

41/54




FIG. 20

42/54




FIG. 21A

43/54




FIG. 21B

44/54




FIG. 22A

45/54




FIG. 22B




FIG. 22C




FIG. 22D1




FIG. 22D




FIG. 22E

46/54




FIG. 22B1

47/54




FIG. 23A




FIG. 23B

48/54




FIG. 24A

49/54




FIG. 24B

50/54






FIG. 25A

51/54



52/54




FIG. 26

53/54




FIG. 27A

54/54




FIG. 27B